

KOMATSU PC128US-11	
YEAR:	2020YR
HOUR:	2051Hrs
SPEC:	KOMATSU PC128US-11 2020yr 2,051hrs Available
SHOE:	N/A
LOCATION:	YOKOHAMA
PLATE NO.:	N/A
STAMP:	N/A

ENGINE

Maker:	N/A
Model:	N/A
S/No.:	N/A
EXHAUST GAS REGULATIONS:	N/A

CONDITION

Ref No: JMX8798

Detail	Details
Engine	Grade: C - (Oil Leak) Engine bottom oil oozing
Radiator	Grade: C
Operation	Grade: C
Swing Device	Grade: C
Travel (left)	Grade: C - Shoe (steel, roadliner, rubber pad) Rubber pad broken more than 20 pcs
Travel (right)	Grade: C - Shoe (steel, roadliner, rubber pad) Rubber pad broken more than 20 pcs

COMMENTS:

No additional comments.

JAMEX CO., LTD.

English: This inspection information is for reference only. It is not to guarantee the condition of the actual machine. For more information, visit our website at www.jamex.co.jp

Japanese: この査定情報はあくまで参考資料であり、実際の機械の状態を保証するものではありません。詳細については、当社ウェブサイト www.jamex.co.jp をご覧ください。

Generated on: 2026-07-21 22:45:17

Machine ID: JMX8798